

Detroit District P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L03-77	Date: 14 OCTOBER 2003

Waterway: LAKE HURON Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL TAWAS BAY HARBOR

- 1. Condition surveys performed within the Federal navigation channel at Tawas Bay Harbor, Michigan during September 2003, indicate shoaling as shown on the back of this sheet.
- 2. Mariners are urged to use extreme caution in the area.
- 3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L03-77. Internet address: http://www.lre.usace.army.mil Go to: Detroit Home Page, Who We Are, Operations Home Page.

THOMAS H. MAGNESS Lieutenant Colonel, U.S. Army District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2003.



The information depicted on this map represents the results of surveys made on the dates indicated and can only be considered as indicating the conditions existing at that time.

Surveys taken: SEPTEMBER 2003

Shoals indicate least available depth below IGLD.

TAWAS BAY HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 14 OCTOBER 2003

U.S. Army Engineer District, Detroit

0tawas.bmp